

BEC Spares List - January 2004

Book				
Berkeley Sportscars - Road Test Ltd. Edition,				
Brooklands Books	10.00	1.00		
Front Wheel Cylinder Overhaul Kit				
MB107/14 SE328, early SE492	10.00	0.50		
MB127/13 SE492, T60, B95	10.00	0.50		
Rear Wheel Cylinder Overhaul Kit				
MB107/13 SE328, early SE492	6.00	0.50		
MB127/27 late SE492, B95	7.00	0.50		
MB127/28 T60	3.50	0.50		
Master Cylinder				
MB107/19 Complete Assembly				
(suitable for ALL models)	58.00	4.00		
MB107/24 Overhaul Kit	6.00	0.50		
Front Wheel Cylinders				
MB107/11,12 SE328, early SE492	10.00	1.00		
MB107/33,34 late SE492, B95, T60	11.00	1.00		
Rear Wheel Cylinders				
MB127/25,26 late SE492, B95, T60	12.00	1.00		
Brake Hoses (pair)				
MB107/29,30 Front, late SE492, B95, T60 .	15.00	2.50		
MB127/22,23 Rear, late SE492, B95, T60 ..	15.00	2.50		
Brake Hoses				
MB339/10 Front (14") ALL models	12.00	1.20		
MB339/11 Rear (12½") ALL models	11.00	1.20		
Hand Brake Cables				
MB1025/2 SE328/492, B95 Secondary ..	24.00	1.50		
MB1063/1 T60 Primary (straight-pull) ...	26.00	1.50		
MB1063/2 T60 Secondary (straight-pull)	10.00	0.75		
Front Axle				
MB141/6 Hub Oil Seal	6.00	0.50		
MB107/1 Hub/Brake Drum	75.00	7.50		
MB1177/5 Stub Axle Nut	5.00	1.00		
MB166/3 Hub Bearing	14.00	1.00		
MB1095 Wheel Stud (each)	2.50	0.25		
MB Wheel Nut (each)	1.00	0.50		
MB1177/7 Wheel Trims/Spinners (pair) .	25.00	4.00		
MB1177/6 Spinners (pair)	10.00	1.20		
Rear Axle				
MB166/6 Hub Oil Seal	6.00	0.50		
MB166/3 Hub Bearing (large)	14.00	1.00		
MB166/4 Hub Bearing (small)	11.00	1.00		
MB248 Stub Axle Nut	0.50	SAE		
Front & Rear Suspension				
MB130/142 King Pin				
MB130/143 Trunnion } refurb/exchange .	60.00	5.00		
MB163 Bottom Wishbone Stud	4.00	1.00		
MB159/1 Front Wishbone Bush	8.00	0.50		
MB173/3 Rear Wishbone Bush	10.00	0.50		
MB1085 T60 Swinging Arm Bush	11.00	0.50		
Steering				
2010 Idler Lever Bush (fits within).	9.00	0.50		
2063 Centre Trackrod Bush	OOS			
Final Drive				
MB122 Large Differential Nut	1.00	0.50		
MB120 Small Differential Nut	0.50	SAE		
MB115/1 Differential O Ring	0.50	SAE		
MB242 Differential Shaft Key	1.00	SAE		
MB110/5 Drive Housing Bearing	14.00	1.00		
MB141/6 Drive Housing Oil Seal	6.00	0.50		
MB108/8 Universal Joint (with nipple)..	13.00	1.50		
Anzani Engine				
-	322 Gasket Set	6.50	0.75	
1715 Crankcase Oil Seal	3.00	0.50		
Excelsior Engine				
-	244 Gasket Set	6.50	0.75	
-	328 Gasket set	9.50	0.75	
3046 Clutch Cover Gasket	1.00	SAE		
3045 Backplate to Crankcase Gskt.	0.50	SAE		
3041 Inlet Manifold Gasket	0.50	SAE		
3202 Cylinder Base Gasket	0.60	SAE		
3221 Carb/Manifold Gasket	0.60	SAE		
3016 Crankshaft Nut	6.50	SAE		
1101 Front Engine Mounting	25.00	1.75		
1102 Rear Engine Mounting	35.00	2.00		
-	Rear Engine Mntg Bolt	5.00	1.50	
3066 Crank Oil Seal - Drive Side ..	4.50	0.50		
3070 Crank Oil Seal - Centre	4.00	0.50		
3072 Crank Oil Seal - Timing Side	4.00	0.50		
3065 Ball Bearing - Drive Side	32.00	1.50		
3158 Roller Bearing - Centre	25.00	1.50		
3090 Roller Bearing - Timing Side	25.00	1.50		
3157 Dynastart Flywheel Nut	6.50	1.50		
Royal Enfield Engine				
-	Drive Cover Oil Seal (large) .	7.50	0.50	
-	Drive Cover Oil Seal (small).	6.00	SAE	
1605 Crankshaft Nut	10.00	1.50		
1605/5 Flywheel (unmachined)	25.00	5.00		
1605/6 Starter Ring	60.00	3.00		
Clutch				
MB1009 Clutch Cable (Excelsior)	23.00	1.50		
HJ55(63) Clutch Backplate Nut	3.00	SAE		
VR42,43(3,4) Lever Adjuster Pin & Sleeve.	5.00	SAE		
TR66C(8) Adjuster Sleeve Thrust Pad ..	3.50	SAE		
VR66B(10) Push Rod Thrust Pad	4.00	SAE		
H66B(49) Push Rod End Piece	3.50	SAE		
H66/0901(48) Push Rod (cut/harden to suit)	2.00	0.50		
G70(78) Cush Drive Rubbers (set) ..	9.00	0.50		
Carburettors/Fuel				
-	Amal 376 gasket set (Exc) ...	1.50	SAE	
MB379/4 Throttle Cable 20"				
	(conical nipple)	7.00	0.75	
MB1622 Throttle Cable 24"				
	(state pedal & type) .	7.50	0.75	
MB379/48 Choke Cable 40" (ALL)	8.00	0.75		
1122 Brass Union (fuel line)	1.00	SAE		
385 Petrol Tank Cap SE328/T60	2.00	0.50		
MB1120/3 Petrol Filler Cap SE492/B95	14.00	0.50		
MB1120/4 Petrol Filler Neck SE492/B95	3.00	0.50		
MB220/11 Petrol Gauge (substitute)	25.00	1.50		
General Electrical				
MB1154 Wiring Loom T60	90.00	4.00		
MB1154 Wiring Loom B95	90.00	4.00		
MB331 Ignition Switch (inc Keys)	OOS			
-	Miniature Pull Switch SE328	8.00	0.50	
MB1066 Push Button Switch, black				
	(Horn & Starter) .	OOS		
MB1068 ON-OFF Switch, black				
	(Wiper & Panel Backlight) .	OOS		
MB1069 ON-ON-OFF Switch, black				
	(Headlight/Sidelight) ..	13.00	0.50	
MB715 Warning Light, Red or				
	Green SE492/B95 .	9.00	0.30	
101 Siba Dynastart Brushes	OOS			

Indicators

MB324	Rotary Switch SE328, T60	10.00	1.00
-	Rotary Switch SE492, B95	5.00	0.50
MB753	Column Stalk (illuminated) ...	52.00	1.00
	Column Stalk (plain)	28.00	1.00

Excelsior Ignition

MB388	Ignition Coil	OOS	
MB209	Contact Breaker Set (pair)	OOS	
39	Siba Condenser	2.00	0.30
FCAX1	SE492 Large Points Backplate & Cam Conversion ..	25.00	1.00

Lamp Assemblies

MB745	Rear Stop/Tail Lamp Conical Glass Lens Late Models ..	9.00	1.00
MB344	Rear Stop/Tail Lamp Flat Glass Lens Early SE328 ..	9.00	1.00
MB325	Indicator Lamp Conical Glass Lens Late Models ..	9.00	1.00
MB325	Indicator Lamp Flat Glass Lens Early SE328 ..	9.00	1.00
MB719	Rear Reflector (Red) similar to lamps later Models.	7.00	1.00
MB726	Rear Number Plate Lamp Chrome SE492, B95 ..	16.00	1.00
-	Rear Stop Lamp. Oval SE492, B95 ..	7.00	1.00
MB334	Lens D Shape SE328	3.00	1.00

Speedo & Tacho

MB326/1	Speedometer Cable	23.00	1.50
MB1159/2	Tacho Cable	26.00	1.00
-	Berkeley Tacho Dial Face	45.00	SAE

Body

MB230	Slanted Door Hinges (pair) early SE328/SE492 ..	40.00	2.50
-	External Door Hinges (alloy) T60	45.00	2.50
-	Alloy Bonnet Hinges T60	35.00	1.50
-	Gearlever Quadrant 4-Speed (chrome plated) ..	OOS	
MB232	Front Grille, Diamond Mesh Alloy SA322/SE328 ..	8.00	4.00
MB736	Front Grille, Square Mesh Chrome SE328/492, T60 ..	70.00	4.50
MB400/11	"Berkeley" Bonnet or Steering Wheel Badge Chrome/Enamel single stud and fixing bush	20.00	1.00
MB857/2	Steering Column Badge Rubber Bush all models ..	0.70	SAE
MB1158/1	Hood Frame late SE492, B95 ..	55.00	5.00
-	Lift-the-Dot Fastener	0.40	SAE
-	Lift-the-Dot Stud & Nut	0.40	SAE
MB	Upholstered Seat Squab (Grey) for Bench Seat SE328	150.00	7.00
-	Seat Webbing Clips (all models) ...	0.20	SAE
-	Elastic (all models) per metre	1.20	0.15
-	Chrome Door Lock Handle SE492, B95 ..	4.00	1.20
-	Door Locks (internal fit) SE328, T60 ..	6.00	1.50
-	Parcel Cover Lock (budget) LH SE328/492, B95	4.00	1.20
	RH SE328	4.00	1.20
	T' Key (fits LH & RH) ..	2.00	1.20

MB348	Bonnet Lock (pear shaped, with keys) SE328/492, T60 ..	11.00	1.50
-	Bonnet Lock (budget) Mechanism	4.00	1.20
	Chrome Cover/Flap	6.00	0.50

Windscreen

MB299/4	SE328/492 (early)	120.00	*
-	SE492, B95	170.00	*
-	T60 (hardtop)	140.00	*
-	T60 (soft top)	100.00	*

Anzani Exhaust

-	Twin Pipe & Boxes	120.00	*
-	Flanges	24.00	*
-	Gasket	0.75	SAE

Excelsior Exhaust

-	Twin (siamese)	OOS	*
-	Twin (across-front)	OOS	*
-	Triple (across-front)	110.00	*

ALL EXCHANGE MOUNTING FLANGES

MB1000/22	Gasket 3043 (each)	2.00	0.30
------------------	--------------------------	------	------

* plus transport costs or collection to be arranged.

The club also holds a stock of second hand parts. These items are generally sold on an exchange (badly-worn for less-worn) basis and include engine, transmission, steering, suspension and brake components/assemblies.

NOTE

- ALL enquiries to be made by LETTER ONLY to BEC Spares at the address listed on the *Club Contacts* page. When requesting details of new spares or second hand items please send an SAE.
- BEC Spares is run by volunteers and all profits are re-invested in the club spares scheme.

Payment

Cheques, international money orders, etc. to be made payable to "BEC Spares" in £ sterling only. Sterling cash or travellers cheques are also acceptable.

Postage

Multiple orders may attract lower rates. Figures quoted are for UK delivery only - overseas customers please ask.

Pistons

New Excelsior piston assemblies (std, +20, +30, +40 and +60 thou.) are available from:
John Chatt, F.W. Thornton & Sons, 57 Wyle Cop, Shrewsbury, Shropshire, SY1 1YJ. Tel: 01743-357081.

Suspension Units

Damper units, springs, bushes and complete assemblies are available from:
Hagon Products, 7 Roebuck Road, Hainault, Essex, IG6 3JH. Tel: 0208-502-6222.

NOTE

State front/rear, length and exact Berkeley model.

Various Items

Hoods, headlamp covers/fixings, brake pipe sets, T60 hood frames/fixings are available from:
Dave Ratner, Berkeley Developments, 105 Ebenezer Street, Langley Mill, Nottinghamshire, NG16 4AD.
Tel: 01773-713174.